

# Quality and Utility Assessment of Completed EPA's

District: Baghalpur Project Title: Baghalpur WDC-I/2021-22

Block: Kahalgaon Panchayat: Ektara Village: Ektara Beneficiary Name: Dharmendra Kumar Das

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
1865A	Structure: <u>Chabutra</u>	<u>25.19 44</u> <u>87.19 ' 1</u>	<u>100 %</u>	<u>100 %</u>	<u>80 %</u>	<u>20 %</u>	<u>0 %</u>	<u>60 %</u>

Remark (Overall Quality & Utility of Structure):

कार्य रूपल अ - यमन कीक है। लेकिन कार्य अ - गुणवत्ता कीक नहीं है।  
यबदुरा टुटा हुआ है - एवम इलाका - कीक उपयोग - नहीं है -  
भीकना अ कीक लगा हुआ है -

Visit Date:- 14-3-2024

Name:- Koshal Kumar Das

Signature:- Koshal Kumar Das