

Quality and Utility Assessment of Completed EPA's

District: Bhojpur

Project Title: Bhojpur

-WDC-I /2021-22

Block: Koilwar

Panchayat: Khangaon

Village: Khangaon

Beneficiary Name: Jay prakash Singh

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
4525	Structure:	25.81175	100%	100%	100%	100%	100%	100%
	Chabutra	84.753022						

Remark (Overall Quality & Utility of Structure):

कार्य स्थल का पथन एवं कार्य कि गुणवत्ता अच्छी है। आस पास ज़ामिनी द्वारा चबुतरा का उपयोग करके अन्य कार्य कर रहे हैं जो कि चबुतरा पर ही डिस्पल का पाया गया है जिसका पुरा विवरण अंकित है।

Visit Date:- 09/10/2023 (13.32)

Name:- Amit Kumar Singh

Signature:- Amit Kumar Singh