

Quality and Utility Assessment of Completed EPA's

District: ARWAL Project Title: ARWAL -WDC-I /2021-22

Block: BANSHI Panchayat: MALI Village: MALI Beneficiary Name: KAMTA BAND

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
17757	Structure: HAND PUMP	25.127604 84.703973	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कमल-बंद का चमक एवं चमक की गुणवत्ता ठीक है; जो कि
ग्रामियों के अनुसार हैंडपंप का उपयोग उनके द्वारा किया
जाता है। कमल पद पर डिपलें कीड नहीं पाया गया।

Visit Date:- 06/12/23

Name:- NIRAJ KUMAR

Signature:- Niraj Kumar