Quality and Utility Assessment of Completed EPA's

District: Aurangabad, Project Title: PMKSY20-WDC-I/2021-22, Panchayat: Baranda Rampur, Village: Pachmo, Beneficiary Name: Suryader Paswan Block: Deo

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
1	Structure: Hand tube well with soak pit	24.564281	100 %	100 %	100%	190%.	40%	88
18	WHY SOUR PIE	84.388381						

Remark (Overall Quality & Utility of Structure):

Structure की 1501वला अच्छी है, लेकिन कम जलहतर होने के कहन वर्तमान में उपयोग में नहीं है। structure के पास display board लगा दुआ है।

Visit Date: - 25.09.23

Name: - Shishupal

signe - Shishupal