

### Quality and Utility Assessment of Completed EPA's

District: Aurangabad , Project Title: PMKSY 2.0 -WDC- I/2021-22

Block: Kutumba ,Panchayat: Dumri ,Village: Mahshu ,Beneficiary Name: Khedu Yadav

| Work ID | Name/ description of activity       | Latitude & Longitude | Work Identification<br>(Excellent 100%,<br>good 80%,<br>average 60%,<br>poor 40%) | Site Identification<br>(Excellent 100%,<br>good 80%,<br>average 60%,<br>poor 40%) | Specification<br>Followed<br>(Totally 100%,<br>Mostly 80%,<br>Average 60%<br>Poor 40%) | Physical Appearance<br>of Structure<br>(Excellent 100%,<br>good 80%,<br>average 60%,<br>poor 40%) | Utility of Structure<br>(In full use 100%,<br>partially used 80%,<br>Yet to be used 70%,<br>Occasionally used 60%<br>Not used/rarely used 40%) | Average<br>Score |
|---------|-------------------------------------|----------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|----------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|------------------|
| 1       | 2                                   | 3                    | 4                                                                                 | 5                                                                                 | 6                                                                                      | 7                                                                                                 | 8                                                                                                                                              | 9                |
| 18959   | Structure:<br>Renovation of<br>well | 24.590902            | 100 %                                                                             | 100 %                                                                             | 100 %                                                                                  | 100 %                                                                                             | 100 %                                                                                                                                          | 100              |
|         |                                     | 84.335997            |                                                                                   |                                                                                   |                                                                                        |                                                                                                   |                                                                                                                                                |                  |

**Remark** (Overall Quality & Utility of Structure):

कार्यस्थल एवं structure की गुणवत्ता अच्छी है, लाभार्थी द्वारा खेत में पक्क  
और पानी पिन के लिए उपयोग में है। structure के पास display board  
नहीं पाया गया।

Visit Date :- 06.10.23

Name :- Shishupal

Sign :- Shishupal