

Quality and Utility Assessment of Completed EPA's

District: BANKA Project Title: BANKA -WDC- II /2021-22

Block: Katoriya Panchayat: Damodara Village: Amagachhi Beneficiary Name: Srimati marandhi

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18868	Structure: Chabutra	24.722048 86.790375	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

गुणवत्ता एवं उपयोगिता का परीक्षण करने के लिए आगमन किया गया। चबूतरा का निर्माण ठीक प्रकार से हुआ है। चबूतरा पर बैठने के लिए उपयोगी है। चबूतरा पर बैठने के लिए उपयोगी है। चबूतरा पर बैठने के लिए उपयोगी है।

Visit Date:- 21/12/23

Name:- Brindaban Mahto

Signature:- Brindaban