

Quality and Utility Assessment of Completed EPA's

District: ARWAL

Project Title: ARWAL

-WDC-1 /2021-22

Block: BANSHI

Panchayat: KHARASIN

Village: PAHARPUR

Beneficiary Name: AJAY KUMAR PATHAK

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
17735	Structure: HANDPUMP	25.102457 84.667158	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कोमल का चमक एवं फर्श की गुणवत्ता ठीक है। ग्रामियों के अनुसार
हैंडपंप का उपयोग किया जाता है, अतः यह ग्रामियों के लाभप्रद
का है। स्थल पर पर डिस्पले बोर्ड नहीं पाया गया।

Visit Date:- 05/12/23

Name:- NIRAJ KUMAR

Signature:- Niraj Kumar