

Quality and Utility Assessment of Completed EPA's

11

District: Begusarai Project Title: Begusarai -WDC- I /2021-22

Block: Bixpur

Panchayat: Jagdar

Village: Muxadpur

Beneficiary Name: Savita Devi

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
458	Structure: Construction of Chabutra		60%	100%	100%	60%	80%	80%

Remark (Overall Quality & Utility of Structure):

कार्य स्थल का चयन अच्छा है। लेकिन गुणवत्ता बहुत खराब है। चबुतरा चारों तरफ से फ्रेम है। चबुतरा का नीचला हिस्सा दिवार और ऊपरी हिस्सा स्लैब के बीच फ्रेम ज्यादा है। स्कूल में चबुतरा का निर्माण हुआ स्कूल के छात्रों के उपयोग में है। चबुतरा पर स्लैब डिस्पले बोर्ड लगा हुआ है। जिसमें विवरण आबोत है।

Visit Date:- 08-12-2023

Name:- Umesh Yadav

Signature:- UYadav