

Quality and Utility Assessment of Completed EPA's

District: Bhojpur Project Title: Bhojpur -WDC- I /2021-22

Block: Asi Sadar Panchayat: Daulatpur Village: Daulatpur Beneficiary Name: Kapilmuni Singh

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
4320	Structure: <u>Chabutra</u>	<u>23.598694</u>	<u>80%</u>	<u>80%</u>	<u>80%</u>	<u>80%</u>	<u>40%</u>	<u>50%</u>
		<u>84.688368</u>						

Remark (Overall Quality & Utility of Structure):

कार्य स्थल एवं कार्य की गुणवत्ता ठीक है, जो कि ग्रामिणों द्वारा चकुरा का उपयोग किया जा रहा है, और डिस्पलॉय नहीं है।

Visit Date:- 08-02-2024 (10:02)

Name:- Amit Kumar Singh

Signature:- Amit Kumar Singh