

Quality and Utility Assessment of Completed EPA's

District: ARWAH Project Title: ARWAH -WDC- 1 /2021-22

Block: KARPI Panchayat: SHAHARTALPA Village: MAYABAGH Beneficiary Name: SATENDRA RAJBANSI

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
17753	Structure: Construction of CHABUTRA	25.133565 84.666935	100%	100%	100%	60%	100%	92%

Remark (Overall Quality & Utility of Structure):

कच्चा बंधल का चमन अच्छा है, लेकिन इसकी गुणवत्ता खराब है;
चबुतरा का उपरी हिस्सा एवं चारों तरफ से फ्रेम है। चबुतरा
का उपयोग झाड़ियों द्वारा अलग-अलग कमों में किया जाता
है, स्थल पर डिस्पले और फाग गम।

Visit Date:- 05/12/23

Name:- NIRAJ KUMAR

Signature:- Niraj Kumar