

Quality and Utility Assessment of Completed EPA's

District: Baghalpur Project Title: Bhalpur -WDC- I /2021-22

Block: Kahalgaon Panchayat: Rampur Village: Lokita Beneficiary Name: Asha Kumaari

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18660	Structure: Renovation of well	25.273753 87.810225	60 %	60 %	100 %	80 %	0 %	60 %

Remark (Overall Quality & Utility of Structure):

कार्य स्वयं एवं कार्य - अनुपलब्ध है - जो कि ग्रामीणी - द्वारा - इत - बोल - री -
पहले परवत करायो - जास - या - अभी वर्तमान - में - में - बोल - बिलकुल - सुका है -
अभी - इतने लकड़ी - का - जलावन - बरगार - के - लिए - बकका किया - जा रहा - है -
ग्रामीणी - के - अनुसार - कुत्ता - में - अभी - पानी - नहीं - रहता - है -
भीजना व बार्ड - लगा हुआ है

Visit Date:- 14-3-2024

Name:- Koshal Kumar

Signature:- Koshal Kumar