## Quality and Utility Assessment of Completed EPA's

District: Aurangabad, Project Title: PMKSY 20 -WDC- I/2021-22

Block: Deo ,Panchayat: Dulare ,Village: Tharna ,Beneficiary Name: Birendra Kumar

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18955	Structure: Chabutra	24·530793 84·367044	100%	(00 %	100%	100%	100%	100

Remark (Overall Quality & Utility of Structure):

Structure af Jouann 3120 & about & structure of display board of all \$30 &1

Visit Date: - 25.09.23

Name: - Shishupal

sign: - Shishufal