

Quality and Utility Assessment of Completed EPA's

District: Bhopur Project Title: Bhopur -WDC-I /2021-22

Block: Arasgarh Panchayat: Gauthayla Village: Bhubala Beneficiary Name: Basudha Singh

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
4517	Structure: Handpump	25.536777 84.684555	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्य स्थल एवं कार्य की गुणवत्ता ठीक है। जो आसिणी द्वारा पापारुल का उपयोग किया जा रहा है। जो कि डिस्पर्ल बोर्ड पापारुल पर लि आंकित है

Visit Date:- 08/10/2023 (10:34)

Name:- Amit Kumar Singh

Signature:- Amit Kumar Singh