

Quality and Utility Assessment of Completed EPA's

District: BANKA **Project Title:** BANKA -WDC- II/2021-22

Block: Katoriya **Panchayat:** Damodara **Village:** Burighat **Beneficiary Name:** Raghu Mandal

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18861	Structure: Renovation of Well	24.72376 86.805255	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्पस-एल कार-यमन एवं कारी करि गुणवत्ता अच्छी है, ग्रामिणी द्वारा
कुआँ कार उपयोग लिया जाता है, कुआँ पर योजना संवदन
दिखा हुआ है।

Visit Date:- 11/12/2023

Name:- Brindaban Mahto

Signature:- Brindaban