## **Quality and Utility Assessment of Completed EPA's**

	Distric	t: BANKA Proje	ect Title: BA	NKA -	WDC- <u>∭</u> /20	021-22		
Block:	Chandan Panch	ayat: Silzwi	Beneficiary Name: Bhubal Jaclar					
Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
882c	henovation of Well	24.596935 86.670422	100%.	100%	100%	10-04.	100%	1004,
Remark (Overall Quality & Utility of Structure):  ONTHE ONE SHOW OF STREET STRE								
Visit Dat	te:- 20/12/23	>	Name:- Bal	notation	Manto	Signature:-	Leindalson	