

Quality and Utility Assessment of Completed EPA's

District: BANKA Project Title: BANKA -WDC-III /2021-22

Block: Chandan Panchayat: Silzari Village: Baghmari Beneficiary Name: Shiv Narayan Mandal

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18778	Structure: Renovation of Well	24.575881 86.67857	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्य-पत्र का काम एवं कार्य की गुणवत्ता अच्छी है,
कार्य की गतिमति के अनुसार है और इस का उपयोग किया
जाता है, और यह योजना विवरण सिद्ध हुआ है।

Visit Date:- 12/12/23

Name:- Brindaban Manta Signature:- Brindaban