

Quality and Utility Assessment of Completed EPA's

District: BANKA Project Title: BANKA -WDC- II/2021-22

Block: Katoriya Panchayat: Damodara Village: Barmashiya Beneficiary Name: Ganiya Dasi

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18862	Structure: Renovation of Well	24.738045 86.818473	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्पिस्थल का चपन रख कार्पि की गुणवत्ता अच्छी है, जो कि ग्रामिणों द्वारा कुआँ का उपयोग किया जाता है, कुआँ पर योजना विकास विभाग तैयारी हुआ है।

Visit Date:- 21/12/23

Name:- Brindaban Mahato

Signature:- Brindaban