

### Quality and Utility Assessment of Completed EPA's

District: **BANKA** Project Title: **BANKA** -WDC- **I/2021-22**

Block: **Katoriya** Panchayat: **Lakrama** Village: **Lakrama** Beneficiary Name: **Swirji Devi**

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18662	Structure: Chabutra	24.61396 86.892187	100%	100%	100%	100%	100%	100%

**Remark** (Overall Quality & Utility of Structure):

कार्यस्थल का चयन एवं कार्य की गुणवत्ता अच्छी है, जो कि ग्रामिणों द्वारा चक्रवात का निर्माण करने के लिए उपयोगी है, स्थल पर सिंचने के लिए पानी पाया गया;

Visit Date:- **14/12/23**

Name:- **Brindaban Mahto**

Signature:- **Brindaban**