

Quality and Utility Assessment of Completed EPA's

District: BANKA Project Title: BANKA -WDC-III/2021-22

Block: Chandan Panchayat: Chandan Village: Chandan Beneficiary Name: Iman Angari

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18841	Structure: Renovation of Well	24.6224 75 86.6623 14	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

लापर-वाह का काम सब काम की गुणवत्ता अच्छी है जो
के कामियों के अनुसार हुआ है और कि उपयोग किया
जाता है, हुआ पर योजना विवरण लिखा हुआ है।

Visit Date:- 12/12/23

Name:- Brindaban Mahato Signature:- Brindaban