

Quality and Utility Assessment of Completed EPA's

District: BANKA Project Title: BANKA -WDC- II /2021-22

Block: Katoriya Panchayat: Targachha Village: Pakerawakala Beneficiary Name: Ramesh Marandi

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18899	Structure: Hand Pump	24.755757	100%	100%	100%	100%	100%	100%
		86.757366						

Remark (Overall Quality & Utility of Structure):

व्यावस्थिकता और चयन एवं कार्य और सुखावता अच्छी है जो कि ग्रामिणों को अनुकूल है इसमें और उपयोग किया जाता है, स्थल पर डिस्पले बोर्ड लगा गया।

Visit Date:- 18/12/23

Name:- Brindaban Mahato Signature:- Brindaban