

Quality and Utility Assessment of Completed EPA's

District: BANKA **Project Title:** BANKA **-WDC-II /2021-22**

Block: Katoriya **Panchayat:** Barbagani **Village:** Barbagani **Beneficiary Name:** Dinesh Kumar Diwakar

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18866	Structure: Renovation of Well	24.803405 86.77715	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्पसलर का वजन एवं लॉपि की गुणवत्ता अच्छी है, जो कि ग्रामिणी शरा अउरों का उपयोग किया जाता है अउरों पर कोलना विवरण, तबिल उडा है।

Visit Date:- 18/12/23

Name:- Brindaban Mahato **Signature:-** Brindaban