## Quality and Utility Assessment of Completed EPA's

District: Baghal Pun Project Title: Baghal ful -WDC-1/2021-22

Block	: Kachelgan Panch	layat: Ramzanipur	Village: Ku	Hapur	Beneficiary	Name: Hat	rendosa Pahar	riya
Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)		Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)		Average Score
1	2	3				poor 4070)	140t used/fatery used 40%)	
	Structure:		4	5	6	7	8	9
100 M	Chabu, fra	25 ' 3037 ' 88 87 '27 2821	10%	1004.	1004.	1001.	100 %	100%

Remark (Overall Quality & Utility of Structure):

6 16

कार्य रमल रवं कार्य की भुणवत्या किंह की कि भाभीशी द्वारा अंबरा
91- 34मीग अफ़त- कर्रहा
91- (34मी) अलग- किट्डा लगा- बच्चे-मादि मिलाह जिल्ड भेडण में (34मी)।-
भी ली ही । ये इस्ट्रेमर अम लीट लगा हुआ है।

Visit Date: 1-3-2024

Name:- Ko Shal kuma a sto Signature:- Ko Shal kumad so