

Quality and Utility Assessment of Completed EPA's

7

District: Begusarai Project Title: Begusarai -WDC-I /2021-22

Block: BIRPUR

Panchayat: Parra

Village: Parra

Beneficiary Name: Saraswati Devi

| Work ID | Name/ description of activity | Latitude & Longitude | Work Identification (Excellent 100%, good 80%, average 60%, poor 40%) | Site Identification (Excellent 100%, good 80%, average 60%, poor 40%) | Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%) | Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%) | Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%) | Average Score |
|---------|---|------------------------|---|---|--|---|--|------------------|
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 |
| 454 | Structure: Construction of chabutra | 25.501028 86.103349 | 60% | 100% | 100% | 60% | 100% | 84% |

Remark (Overall Quality & Utility of Structure):

कार्य स्थल का चयन ठीक है। लेकिन गुणवत्ता खराब है। चबुतरा के चारों तरफ ज्यादा फ्रेम है। चबुतरा के निचला हिस्सा दीवार और उपरी हिस्सा स्लाप के बीच ज्यादा है। चबुतरा स्कूल के प्रांगण में बना है स्कूल के बच्चों के उपयोग में है। ग्रामीणों के उपयोग में नहीं है। चबुतरा पर डिस्पले बोर्ड नहीं लगा है।

Visit Date:- 08-12-2023

Name:- Umesh Yadav

Signature:- Umesh Yadav