

Quality and Utility Assessment of Completed EPA's

District: ARWAL Project Title: ARWAL -WDC-I /2021-22

Block: BANSHI Panchayat: KEAL Village: KEAL Beneficiary Name: BEBY KUMAR

| Work ID | Name/ description of activity | Latitude & Longitude | Work Identification (Excellent 100%, good 80%, average 60%, poor 40%) | Site Identification (Excellent 100%, good 80%, average 60%, poor 40%) | Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%) | Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%) | Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%) | Average Score |
|---------|-------------------------------|------------------------|---|---|---|---|---|------------------|
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 |
| 17768 | Structure: HANDPUMP | 25.115702 84.630792 | 100% | 100% | 80% | 60% | 100% | 88% |

Remark (Overall Quality & Utility of Structure):

कर्मस्थल का चयन ठीक है, लेकिन गुणवत्ता बराबर है, हैंडपंप का नीचे का हिस्सा नहीं बना है। लेकिन यह कर्मस्थल के लिए लाभदायक है, स्थल पर डिस्पेंसिंग की नहीं पायी गयी।

Visit Date:- 09/12/23

Name:- NIRAJ KUMAR

Signature:- Niraj Kumar