

Quality and Utility Assessment of Completed EPA's

District: Bhojpur

Project Title: Bhojpur

-WDC-I /2021-22

Block: Arai Sadar

Panchayat: Bakri

Village: milki karwan

Beneficiary Name: Raju Kumar

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
4348	Structure: Hand pump	23 '31 '38'	100%	100%	100%	100%	100%	100%
		84 '39 '28'						

Remark (Overall Quality & Utility of Structure):

कार्य स्थल का चयन एवं कार्य कि गुणवत्ता अच्छी है जो आस-पास के आदिवासियों द्वारा चापाकल का सह उपयोग किया करने है। चापाकल पर हि डिस्पल कर पाया गया है।

Visit Date:- 10/11/2023 (8:17)

Name:- Amit Kumar Singh

Signature:- Amit Kumar Singh