Quality and Utility Assessment of Completed EPA's

District: Aurangasad, Project Title: PMKSY 2.0 -WDC- 1/2021-22

Block: Deo ,Panchayat: Dulare ,Village: Karma ,Beneficiary Name: Krishna Yadar

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
04681	Structure: Hand tube well with Soak pit	24.555126	1 60 %	160 %.	100 %	100 %.	100%	100

Remark (Overall Quality & Utility of Structure):

Structure of sound and strol of manufactor squal fell structure of Display board and Est Est all structure of

Visit Date: - 15.10.23

Name :- shishupal

sign: - Shishupal