

### Quality and Utility Assessment of Completed EPA's

District: Bagalpur Project Title: Bagalpur -WDC- I /2021-22

Block: Kachalgaon Panchayat: Bagalpur Village: EKora Beneficiary Name: Mata devi

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18654	Structure: Chabutra	25.336586 87.310805	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्य स्वतः स्वयं कार्य की- गुणवत्ता थी है. जी- कि- ग्रामीणों- द्वारा -  
अनाद सुखाने एवम वीरुड के लिए उपयोग- किया- जाता- है-  
औरना ३- वीरुड लगा हुआ है.

Visit Date:- 14-3-2024

Name:- Koshal Kumar

Signature:- Koshal Kumar