Quality and Utility Assessment of Completed EPA's

District: Baghal Ped Project Title: Baghal Ped -WDC-J 12021-22

Block: Karhalgan Panchayat: Rampur			Village: Jages hwapa Beneficiary Name: Kamal Paswan						
Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	I	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%,	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%	Average Score	
1	2	3	1		1 001 1070)	poor 40%)	Not used/rarely used 40%)		
1 1	Structure:	·	4	5	6	7	8	9	
Spap	Chabutra	25°28 7061 87. 6041	100%	100 /.	1001.	100-1.	2001.	100%	
Remark	Remark (Overall Quality & Utility of Structure)								

Remark (Overall Quality & Utility of Structure):

अधिया छ। वहिस्ता हुआ। -ही.

Visit Date: - 16-4-2024

Name: - Koshalkuna R Do

Signature: - 1808 pal 1 cm d 200

4 16