

Quality and Utility Assessment of Completed EPA's

District: ARWAL Project Title: ARWAL -WDC- 1/2021-22

Block: BANSHI Panchayat: KEYAL Village: KEYAL Beneficiary Name: SUJEET KUMAR

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
17777	Structure: HANDPUMP	25.120037 84.629837	100%	100%	100%	60%	100%	92%

Remark (Overall Quality & Utility of Structure):

कम स्थल का चयन थी है, लेकिन गुणवत्ता बुरा है। हैंडपंप का निचै का कक्षा नहीं बना हुआ है। हैंडपंप आउट के ठीक बगल में बना हुआ है, जो कि किसानों के लिए यह काम लाभप्रद काम है। स्थल पर पर डिस्पेंस कोई नहीं पाया गया।

Visit Date:- 09/12/23

Name:- NIRAJ KUMAR

Signature:- Niraj Kumar