

Quality and Utility Assessment of Completed EPA's

District: BANKA Project Title: BANKA -WDC- I /2021-22

Block: Katoriya Panchayat: Kalhasar Village: Jhijgi Beneficiary Name: Rashiklal Soren

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18682	Structure: Renovation of Well	24.635495 86.886246	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्यस्थल का चयन एवं कार्य की गुणवत्ता उत्कृष्ट है।
 और भी ग्रामीणों के अनुकूल गुणों का निर्माण उनके
 लिए उपयोगी है।

Visit Date:- 13/12/2023

Name:- Brindaban Mahita

Signature:- Brindaban