

Quality and Utility Assessment of Completed EPA's

District: Aurangabad , Project Title: Pmksy 2.0 -WDC- II/2021-22

Block: Deo

,Panchayat: Banua

,Village: mararPur

,Beneficiary Name: Nand Kumar

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18979	Structure: Chabutra	24.590969 84.430577	100 %	100%	100 %	100 %	100 %	100

Remark (Overall Quality & Utility of Structure):

Structure की गुणवत्ता अच्छी है, लोगो द्वारा सामाजिक कार्य हेतु उपयोग में है।
Structure के पास display board ~~की~~ पाया गया।

visit date:- 15.10.23

Name:- Shishupal

sign:- Shishupal