

Quality and Utility Assessment of Completed EPA's

District: **BANKA** Project Title: **BANKA** -WDC-**II**/2021-22

Block: **Katoriya** Panchayat: **Targachha** Village: **Sauri** Beneficiary Name: **Vakil Yadav**

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18854	Structure: Renovation of Well	24.730222 86.780752	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्पस-थल का चयन एवं कार्य की गुणवत्ता अच्छी है, जो 100% गुणवत्ता के अनुसार हुआ है और निर्माण के उपचारित है, जो 3-4 मीटर तक योजना विवरण गलेगा 33-10 है।

Visit Date:- **21/12/2023**

Name:- **Brinlaban Mahato**

Signature:- **Brinlaban**