

Quality and Utility Assessment of Completed EPA's

District: BANKA

Project Title: BANKA

-WDC- II /2021-22

Block: Katoriya

Panchayat: Marhar

Village: Satiyari

Beneficiary Name: Kamalant Yadav

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18870	Structure: Renovation of Bandh	24.7920 44 86.738035	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कारिस्थल का चयन एवं कार्य करि गुणवत्ता ठीक है, लो/ली
उगमियों डादा बताया गया कि बाँध का उपयोग सिंचाई
आदि में किया जाता है, स्थल पर डिस्पले बोर्ड लगा हुआ है।

Visit Date:- 21/12/23

Name:- Brindaban Mahato

Signature:- Brindaban