

Quality and Utility Assessment of Completed EPA's

District: Begusarai Project Title: Begusarai -WDC- I /2021-22

Block: Teghra

Panchayat: chilhay

Village: Amula

Beneficiary Name: Ramudgar Mahato

| Work ID | Name/ description of activity | Latitude & Longitude | Work Identification (Excellent 100%, good 80%, average 60%, poor 40%) | Site Identification (Excellent 100%, good 80%, average 60%, poor 40%) | Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%) | Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%) | Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%) | Average Score |
|---------|---|-------------------------|---|---|---|---|---|------------------|
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 |
| 450 | Structure: Construction of Soak pit | 25-510 299 86-032443 | 100% | 100% | 100% | 80% | 100% | 96% |

Remark (Overall Quality & Utility of Structure):

कार्य स्थल का चयन रूप कार्य की गुणवत्ता अच्छी है। शाक पीट की बाहरी हिस्सा को
लवार्डर नहीं किया गया है। ग्रामीण इसका उपयोग करते हैं। शाक पीट पर
डिस्पले बोर्ड पाया गया जिसमें विवरण शामिल था।

Visit Date:- 08-12-2023

Name:- Umesh Yadav

Signature:- 