

Quality and Utility Assessment of Completed EPA's

District: BANKA **Project Title:** BANKA -WDC- I/2021-22

Block: Katoriya **Panchayat:** Lakrama **Village:** Marunda **Beneficiary Name:** Bablu Murmu

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18667	Structure: Chabutra	24.590056 86.873689	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्पस्थल का 'चयन' एवं कार्य की गुणवत्ता अच्छी है, जो कि
ग्रामीणों के अनुसार चकुरा का निर्माण उनके लिए
उपयोगी है, एवं चकुरा पर योजना विवरण लिखा हुआ
थाया गया।

Visit Date:- 14/12/2023

Name:- Brindaban Mahato

Signature:- Brindaban