

Quality and Utility Assessment of Completed EPA's

6

District: Begusarai Project Title: Begusarai -WDC- I /2021-22

Block: Barauni

Panchayat: Sahuri

Village: Sahuri

Beneficiary Name: Navin Kumar Singh

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
YSM	Structure: Construction of chabutra	25.483905 86.104541	80	100%	100%	80%	100%	92%

Remark (Overall Quality & Utility of Structure):

कार्य स्थल का चयन ठीक है। मगर गुणवत्ता ठीक नहीं है। चबुतरा के उपरी हिस्सा फर्स पुरा टूट गया है एवं चबुतरा के चारों तरफ कोना टूटा एवं फ्रेम है चबुतरा पर चढ़ने के लिए बनाया गया सीढ़ी का स्टेप टूटा है। चबुतरा स्कूल में बना है इसलिए स्कूल के बच्चों के उपयोग में है। चबुतरा पर डिस्पले बोर्ड लगा था जिसपर विवरण डाला था।

Visit Date:- 08-12-2023

Name:- Umesh Yadav

Signature:- Umesh Yadav