

Quality and Utility Assessment of Completed EPA's

District: BANKA Project Title: BANKA -WDC- II/2021-22

Block: Katoriya Panchayat: Targahha Village: Pakowakala Beneficiary Name: Anita Murmu

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18856	Structure: <u>Chabutra</u>	<u>24.755704</u> <u>86.757291</u>	<u>100%</u>	<u>100%</u>	<u>100%</u>	<u>100%</u>	<u>100%</u>	<u>100%</u>

Remark (Overall Quality & Utility of Structure):

जाय-यह जा-ययन खं जाय जाय गुणवत्ता अच्छी है, जा
जा ग्रामिणी जा अनुदाय-ययतदा जा निमलि अनुदाय
उपयोगि है, ययतदा पद ययना विवरण लिहा हुआ है।

Visit Date:- 18/12/23

Name:- Brindaban Mahato

Signature:- Brindaban