

Quality and Utility Assessment of Completed EPA's

District: BHOJPUR Project Title: BHOJPUR -WDC-I /2021-22

Block: Apna Sadar Panchayat: Gauthaula Village: Bhusaula Beneficiary Name: poosa devi

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
4534	Structure: <u>Chabutra</u>	<u>25.536724</u> <u>84.684328</u>	<u>100 %</u>	<u>100 %</u>	<u>100 %</u>	<u>80 %</u>	<u>80 %</u>	<u>90 %</u>

Remark (Overall Quality & Utility of Structure):

कार्य स्थल एवं कार्य की गुणवत्ता ठीक है। मंदिर के सामने चबुतरा है जो ग्रामीणों के द्वारा भजन - किर्तन करने है। तथा जानवरों का चारा रखने सुरक्षित में उपयोग करने है। जो ग्रामीणों के द्वारा न देख रेख होने के कारण पक्षी उनी पर उड़-पड़ रहे हैं इसी कारण चबुतरा के किनारे टूट-फूट जाया है। डिस्पल कोई आंकिन नहीं है।

Visit Date: 08/10/2023 (10:42)

Name: Amit Kumar Singh

Signature: Amit Kumar Singh