

Quality and Utility Assessment of Completed EPA's

District: Bhagpur

Project Title: Bhagpur

-WDC- L /2021-22

Block: A29 Sadar

Panchayat: Hasanpur

Village: Hasanpur

Beneficiary Name: Nagwanti devi

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
4528	Structure: Chabutra	29.53847 84.702342	100%	100%	100%	100%	80 %	90 %

Remark (Overall Quality & Utility of Structure):

कार्ग स्थल का नयन रख कार्ग कि गुणवत्ता अच्छी है/जो आस-पास के ग्रामिणों द्वारा चबुतरा का उपयोग करते हैं/वेगल का पंड का रख हिस्सा टूट कर चबुतरा पर गिर गया है/चबुतरा का किनारा छट गया है/चबुतरा पर हिस्सिले लॉर्ड पाया गया है जिससे पुरा विवरण अंगित था

Visit Date:- 08/10/2023 (11:30)

Name:- Amit Kumar Singh

Signature:- Amit Kumar Singh