

Quality and Utility Assessment of Completed EPA's

1

District: Begusarai Project Title: Begusarai -WDC- I/2021-22

Block: Teghra

Panchayat: chilhay

Village: Amua

Beneficiary Name: Satyam kumar

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
448	Structure: chabutra	25.510324 86.032276	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्य स्थल का चयन एवं कार्य कि गुणवत्ता अच्छी है। आस-पास के सभी ग्रामिण चबुतरा का उपयोग बैठने एवं किसी कार्य के लिए करते हैं, चबुतरा पर डिस्पले बोर्ड पाया गया जिसमें पुरा विवरण उल्लिखित था।

Visit Date:- 08-12-2023

Name:- Umesh Yadav

Signature:- 