

### Quality and Utility Assessment of Completed EPA's

District: **BANKA** Project Title: **BANKA** -WDC- **II**/2021-22

Block: **Katoriya** Panchayat: **Danodara** Village: **Amagahhi** Beneficiary Name: **Sanjay Murmu**

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18867	Structure: Renovation of Well	24.719674 86.788418	100%	100%	100%	100%	100%	100%

**Remark** (Overall Quality & Utility of Structure):

कार्यस्थल का पथ शर्तों का भी गुणवत्ता अच्छी है, कार्य  
ग्रामियों के द्वारा कुआँ का उपयोग किया जाता है,  
कुआँ पर योजना विवरण - ही रीति कुआँ है।

Visit Date:- **21/12/23**

Name:- **Brindaban Mahato**

Signature:- **Brindaban**