Quality and Utility Assessment of Completed EPA's

District: Aurangabad, Project Title: PMKSY 2.0 -WDC- II/2021-22

Block: Deo ,Panchayat: Bedhna ,Village: Barheta, mahuraun, Beneficiary Name: Laxuman yadar

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18980	Structure: Chabutra	24.586083	100 %	100%	100%	100%	100%	100

Remark (Overall Quality & Utility of Structure):

कार्यस्थल स्व structure की गुणवता अस्ती है लोगों द्वारा सामाणिक कार्य के लिए उपयोग में है। structure के पास DIAPlay board लगा दुआ है।

Visit_Date: - 29.09.23

Name: - Shishupal

sign: - Shishutal