

Quality and Utility Assessment of Completed EPA's

District: BANKA Project Title: BANKA -WDC- I /2021-22

Block: Kateriya Panchayat: Lakrama Village: Patlikha Beneficiary Name: Pawan Kumar

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18689	Structure:	24.618018	100%	100%	100%	100%	100%	100%
	Uhabutra	86.915122						

Remark (Overall Quality & Utility of Structure):

कार्पिन्धल का चयन स्वयं कार्य की गुणवत्ता अच्छी है, जो कि ग्रामियों के अनुसार चकड़ा का निर्माण उनके लिए उपयोगी है, चकड़ा पद योजना विवरण देना उचित है।

Visit Date:- 14/12/23

Name:- Brindaban Mahato

Signature:- Brindaban