

Quality and Utility Assessment of Completed EPA's

District: Bhopur

Project Title: Bhopur

-WDC- 1 /2021-22

Block: 929 Sader

Panchayat: Hajipur
Piprahia

Village: Piprahia

Beneficiary Name: PUTU/ Kumar

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
4533 4527	Structure: Chabutra	25.551204 84.68433	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कार्य स्थल एवं कार्य की गुणवत्ता ठीक है, जो कि कामिनी द्वारा
नियुक्ता का उपयोग किया जा रहा है, एवं इसमें कोई
घाटा नहीं है।

Visit Date:- 08/10/2023 (11:30)

Name:- Amit Kumar Singh

Signature:- Amit Kumar Singh