

Quality and Utility Assessment of Completed EPA's

District: ARWAL Project Title: ARWAL -WDC-2/2021-22

Block: BANSHI Panchayat: BELAURA Village: KONI Beneficiary Name: MOKIM ALAM

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
17776	Structure: HAND PUMP	25.095218 84.717185	100%	100%	100%	80%	100%	96%

Remark (Overall Quality & Utility of Structure):

कॉन्क्रीट का चयन एवं गुणवत्ता ठीक है; लेकिन हैंडपंप का निचोरा का हिस्सा जहाँ फ्रैक हो गया है। हैंडपंप खेत के बगल में बना हुआ है, जो कि किसानों के लिए बड़े काम में लाभदायक है। स्थल पर पर डिप्ले बॉर्ड लगाया गया।

Visit Date:- 11/12/23

Name:- NIRAJ KUMAR

Signature:- Niraj Kumar