

Quality and Utility Assessment of Completed EPA's

District: Bhojpur Project Title: Bhojpur -WDC- 1 /2021-22

Block: Koiliwar Panchayat: Kyungmnggr/Village: Kyungmnggr Beneficiary Name: Kailash Kumar

Work ID	Name/description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Truly 100%, Modely 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	Structure:	3	4	5	6	7	8	9
430	Structure:	25°35'22"	100%.	100%.	100%.	80%.	70%.	80%.
431	Structure:	84°43'27"	100%.	100%.	100%.	80%.	70%.	80%.

Remark (Overall Quality & Utility of Structure):

कार्य स्थल का समय स्तर कार्य की गुणवत्ता अच्छी है पर आसपास के दाल चकुरा का स्तर 34 परा किछा करने है। वीरना - आस करण जमीनी के द्वारा न देख है। ये देख वीर है चरण बना हुआ है। चकुरा स्तर पानी के किनारे का हिस्सा देख जाया है चकुरा का किनारे डिस्पर्ड वॉटर अभी है।

Visit Date:- 10/10/2023 (T: 43)

Name:- Amrit Kumar Singh

Signature:- Amrit Kumar Singh