

(9)

Quality and Utility Assessment of Completed EPA's

District: Begusarai Project Title: Begusarai -WDC-I /2021-22

Block: Bixpur

Panchayat: Bixpur Purvi Village: Bixpur

Beneficiary Name: Dilip choudry

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
452	Structure: Construction of chabutra	25.51463	100%	100%	100%	100%	100%	100%
		86.081183						

Remark (Overall Quality & Utility of Structure):

कार्य स्थल का-वर्तमान रूप गुणवत्ता अच्छा है। चबुतरा का उपयोग ग्रामीणों द्वारा अपने कार्य के लिए किया जाता है। चबुतरा पैड के नीचे बना है जिसके कारण ग्रामीण चबुतरा का उपयोग धरा में बैठने के लिए करते हैं। चबुतरा पर डिस्पले कोइलगा है जिसपर विवरण आबित है।

Visit Date:- 08-12-2023

Name:- Umesh Yadav

Signature:- Umesh Yadav