

Quality and Utility Assessment of Completed EPA's

District: Baghalpur Project Title: Baghalpur-WDC-I /2021-22

Block: Kachalgaoon Panchayat: Mathurapur Village: Mathurapur Beneficiary Name: Binteshwarin uraon

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18638	Structure: Chabutra	25.283247 87.345275	100%	100%	100%	100%	100	100

Remark (Overall Quality & Utility of Structure):

कार्य सफल एवं कार्य की गुणवत्ता हीन है - जो कि ग्रामिणों द्वारा चतुर्तरा ७ -
उपयोग भवन निर्माण में किया जाता है - तथा आनाक गैड चारल
सुरासे का उपयोग में लाने हैं,
तथा भौजना का कोड लगा हुआ है -

Visit Date:- 16-4-2024

Name:- Koshal Kumar Des

Signature:- Koshal Kumar Des