

Quality and Utility Assessment of Completed EPA's

District: Baghalpur Project Title: Baghalpur -WDC- I /2021-22

Block: Kahalgaon Panchayat: Kishanpur Village: Kishanpur Beneficiary Name: Sarita Devi

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18639	Structure: Chabutra	25° 32' 31.37 87° 33' 20.23	100 %	100 %	100 %	80 %	80 %	92 %

Remark (Overall Quality & Utility of Structure):

कार्य रखल एवं कार्य की - गुणवत्ता दी गई है - जो कि ग्रामीणों द्वारा चबुतरा का उपयोग मिले कार्य के लिये कार्य में सुधार के - उपयोग - में लाई है, 2° ईस्ट यर में बॉर्ड नहीं लगा है।

Visit Date:- 16-4-2024

Name:- Koshal Kumar DEO

Signature:- Koshal Kumar DEO