

Quality and Utility Assessment of Completed EPA's

District: **BANKA** Project Title: **BANKA** -WDC- **I** /2021-22

Block: **Katoriya** Panchayat: **Lakrama** Village: **Shadaba** Beneficiary Name: **Nilkamal Tudu**

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18692	Structure: Renovation of Well	24.59924 86.87234	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

आपस-थल का काम रख कर काँच की गुणवत्ता अच्छी है और
कि ग्रामियों को अनुदान के तहत का उपयोग किया जाता है
कुछ घर चलना बिकरन नहीं लिहा कुडा है

Visit Date:- **14/12/23**

Name:- **Brindaban Mahato**

Signature:- **Brindaban**